



Lead Service Line Inventory Template

*Please enter information in the empty box next to each section	Water System Name		Village of Tampico			System ID Number:		1950550		Current Inventory Date:		3/19/2025			
*Please enter totals in the empty box next to each category	Total Service lines:	348	Total Lead:	7	Total Non-Lead:	70	Total Galvanized Requiring replacement:	119	Total Unknown:	152	Website link to Material Inventory:				

Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA". / If address is not a lead and copper sample site mark "N/A"	EXAMPLES: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities Yes (Y) or No (N)	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	EXAMPLES: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	EXAMPLES: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	EXAMPLES: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	EXAMPLES: Lead (L) Galvanized Requiring Replacement (GRR) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
EXAMPLE- 123 Main Street, Citytown, 61234	N/A	N	N	2023	2023	Maintenance Records	C	P	P	NL	N	4/1/2020	Y	2/10/2023	C		
EXAMPLE- 456 Left Street, Citytown, 61234	LP35001	Y	N	1995	1995	Construction Records	G	P	P	NL	N	N/R	N				
EXAMPLE- 789 Right Street, Citytown, 61234	N/A	N	N	1990	1990	Historical Records	UNL	UNL	UNL	NL	N	N/R	N				
EXAMPLE- 101 Middle Road, Citytown, 61234	N/A	N	N	Unknown	Unknown		U	U	U	U		N/R	N				
312 E. Booth St.	N/A	N	N	Unknown	Unknown	Visual Inspection	U	U	P	U							
402 E. Booth St.	N/A	N	N	Unknown	Unknown	Visual Inspection	U	U	C	U							
103 S. Canal St.	N/A	N	N	Unknown	Unknown	Visual Inspection	U	U	G	GRR							
204 N. Fremont St.	N/A	N	N	Unknown	Unknown	Visual Inspection	U	U	G	GRR							
201 S. Fremont St.	N/A	N	N	Unknown	Unknown	Visual Inspection	U	U	C	U							
206 S. Fremont St.	N/A	N	N	Unknown	Unknown	Visual Inspection	U	U	C	U							
209 S. Fremont St.	N/A	N	N	Unknown	Unknown	Visual Inspection	U	U	P	U							
211 S. Fremont St.	N/A	N	N	Unknown	Unknown	Visual Inspection	U	U	C	U							
104 W. Glassburn S	N/A	N	N	Unknown	Unknown	Visual Inspection	U	U	G	GRR							
106 S. Grove St.	N/A	N	N	Unknown	Unknown	Visual Inspection	U	U	G	GRR							
208 N. Joy St.	N/A	N	Y	2020	Unknown	Visual Inspection	Plastic	P	G	NL							
204 E. Kimball St.	N/A	N	N	2020	Unknown	Visual Inspection	Plastic	P	P	NL							
204 W. Kimball St.	N/A	N	N	Unknown	Unknown	Visual Inspection	U	U	G	GRR							
306 W. Kimball St.	N/A	N	N	Unknown	Unknown	Visual Inspection	U	U	G	GRR							
203 S. Lincoln St	N/A	N	N	Unknown	Unknown	Visual Inspection	U	U	G	GRR							
210 S. Lincoln St.	N/A	N	N	Unknown	Unknown	Visual Inspection	U	U	G	GRR							
201 N. Main St.	N/A	N	N	2020	Unknown	Visual Inspection	Plastic	P	G	GRR							
209 S. Main St.	N/A	N	N	Unknown	Unknown	Visual Inspection	U	U	G	GRR							
214 S. Main St.	N/A	N	N	Unknown	Unknown	Survey Response	U	U	C	U							
311 S. Main St.	N/A	N	N	Unknown	Unknown	Visual Inspection	U	U	G	GRR							
311 E. Market St.	N/A	N	N	Unknown	Unknown	Visual Inspection	U	U	G	GRR							
314 E. Market St.	N/A	N	N	Unknown	Unknown	Visual Inspection	U	U	C	U							
405 E. Market St.	N/A	N	N	Unknown	Unknown	Visual Inspection	U	U	G	GRR							
307 W. Third St.	N/A	N	N	2020	Unknown		Plastic	P	U	U							
108 S. Washington	N/A	N	N	2020	Unknown	Visual Inspection	Plastic	P	G	GRR							
104 N. Benton St.	N/A	N	N	2020	Unknown	Visual Inspection	Plastic	P	C	NL							
105 N. Benton St.	N/A	N	N	2020	Unknown	Visual Inspection	Plastic	P	G	GRR							
106 N. Benton St.	N/A	N	N	2020	Unknown	Survey Response	Plastic	P	G	GRR							

204 N. Benton St.	N/A	N	N	2020	Unknown		Plastic	C	U	U								
205 N. Benton St.	N/A	N	N	2020	Unknown	Survey Response	Plastic	P	G	GRR								
207 N. Benton St.	N/A	N	N	2020	Unknown	Visual Inspection	Plastic	P	P	NL								
107 S. Benton St.	N/A	N	N	2020	Unknown	Survey Response	Plastic	P	G	GRR								
201 S. Benton St.	N/A	N	N	2020	Unknown	Visual Inspection	Plastic	P	P	NL								
208 S. Benton St.	N/A	N	N	2020	Unknown	Visual Inspection	Plastic	P	G	GRR								
213 S. Benton St.	N/A	N	N	2020	Unknown	Visual Inspection	Plastic	P	P	NL								
216 S. Benton St.	N/A	N	N	2020	Unknown	Visual Inspection	Plastic	P	C	NL								
202 E. Booth St.	N/A	N	N	Unknown	Unknown	Visual Inspection	U	U	G	GRR								
304 E. Booth St.	N/A	N	N	Unknown	Unknown	Visual Inspection	U	U	C	U								
315 E. Booth St.	N/A	N	N	Unknown	Unknown	Visual Inspection	U	U	P	U								
401 E. Booth St.	N/A	N	N	Unknown	Unknown	Visual Inspection	U	U	P	U								
411 E. Booth St.	N/A	N	N	Unknown	Unknown	Visual Inspection	U	U	G	GRR								
104 E. Fourth St.	N/A	N	N	2020	Unknown	Visual Inspection	Plastic	P	C	NL								
106 W. Fourth St.	LP35002	N	N	2020	Unknown	Visual Inspection	Plastic	P	C	NL								
202 W. Fourth St.	N/A	N	N	2020	Unknown	Visual Inspection	Plastic	P	P	NL								
303 W. Fourth St.	N/A	N	N	2020	Unknown	Survey Response	Plastic	P	C	NL								
304 W. Fourth St.	N/A	N	N	2020	Unknown	Visual Inspection	Plastic	P	C	NL								
305 W. Fourth St.	N/A	N	N	2020	Unknown	Visual Inspection	Plastic	P	G	GRR								
106 N. Fremont St.	N/A	N	N	Unknown	Unknown		U	U	U	U								
108 N. Fremont St.	N/A	N	N	Unknown	Unknown	Survey Response	U	U	C	U								
103 S. Fremont St.	N/A	N	N	Unknown	Unknown	Visual Inspection	U	U	P	U								
108 S. Fremont St.	N/A	N	N	Unknown	Unknown	Visual Inspection	U	U	C	U								
110 S. Fremont St.	N/A	N	N	Unknown	Unknown	Visual Inspection	U	U	G	GRR								
205 S. Fremont St.	N/A	N	N	Unknown	Unknown	Visual Inspection	U	U	C	U								
202 W. Glassburn S	N/A	N	N	Unknown	Unknown	Visual Inspection	U	U	G	GRR								
307 W. Glassburn S	N/A	N	N	Unknown	Unknown	Visual Inspection	U	U	C	U								
108 N. Grove St.	N/A	N	N	Unknown	Unknown	Visual Inspection	U	U	C	U								
102 S. Grove St.	N/A	N	N	Unknown	Unknown	Visual Inspection	U	U	C	U								
200 S. Grove St.	N/A	N	N	Unknown	Unknown	Visual Inspection	U	U	C	U								
306 N. Joy St.	N/A	N	Y	2020	Unknown	Visual Inspection	Plastic	P	P	NL								
307 N. Joy St.	N/A	N	N	2020	Unknown	Visual Inspection	Plastic	P	C	NL								
106 S. Joy St.	N/A	N	N	Unknown	Unknown	Survey Response	U	U	G	GRR								
208 S. Joy St.	N/A	N	N	Unknown	Unknown	Visual Inspection	U	U	P	U								
209 S. Joy St.	N/A	N	N	Unknown	Unknown	Visual Inspection	U	U	C	U								
100 W. Kimball	N/A	N	N	Unknown	Unknown	Survey Response	U	U	G	GRR								
104 E. Kimball St.	N/A	N	N	Unknown	Unknown	Visual Inspection	U	U	P	U								
307 E. Kimball St.	LP35008	N	N	2020	Unknown	Visual Inspection	Plastic	P	P	NL								
308 E. Kimball St.	N/A	N	N	2020	Unknown	Visual Inspection	Plastic	P	C	NL								
105 W. Kimball St.	N/A	N	N	Unknown	Unknown	Visual Inspection	U	U	G	GRR								
202 W. Kimball St.	N/A	N	N	Unknown	Unknown	Visual Inspection	U	U	G	GRR								
302 W. Kimball St.	N/A	N	N	Unknown	Unknown	Visual Inspection	U	U	G	GRR								
307 W. Kimball St.	N/A	N	N	2020	Unknown	Visual Inspection	Plastic	P	C	NL								
406 W. Kimball St.	N/A	N	N	Unknown	Unknown	Visual Inspection	U	U	C	U								
408 W. Kimball St.	N/A	N	N	Unknown	Unknown	Survey Response	U	U	C	U								
501 W. Kimball St.	N/A	N	N	Unknown	Unknown	Visual Inspection	U	U	G	GRR								
108 N. Lincoln St.	N/A	N	N	2020	Unknown	Visual Inspection	Plastic	P	G	GRR								
205 N. Lincoln St.	N/A	N	N	2020	Unknown	Visual Inspection	Plastic	P	L	L								
305 N. Lincoln St.	N/A	N	N	2020	Unknown	Visual Inspection	Plastic	P	G	GRR								
308 N. Lincoln St.	N/A	N	N	2020	Unknown	Visual Inspection	Plastic	P	G	GRR								
205 S. Lincoln St.	N/A	N	N	Unknown	Unknown	Visual Inspection	U	U	L	L								
208 S. Lincoln St.	N/A	N	N	Unknown	Unknown	Visual Inspection	U	U	C	U								
212 S. Lincoln St.	N/A	N	N	Unknown	Unknown	Visual Inspection	U	U	G	GRR								
206 A S. Main Pl.	N/A	N	N	Unknown	Unknown	Visual Inspection	U	U	C	U								
205 N. Main St.	N/A	N	N	2020	Unknown	Survey Response	Plastic	P	G	GRR								
206 N. Main St.	N/A	N	N	2020	Unknown	Visual Inspection	Plastic	P	C	NL								
209 N. Main St.	N/A	N	N	2020	Unknown	Visual Inspection	Plastic	P	G	GRR								
212 N. Main St.	N/A	N	N	2020	Unknown	Visual Inspection	Plastic	P	G	GRR								
306 N. Main St.	N/A	N	N	2020	Unknown	Visual Inspection	Plastic	P	G	GRR								
205 S. Main St.	N/A	N	N	Unknown	Unknown	Visual Inspection	U	U	G	GRR								
206 S. Main St.	N/A	N	N	Unknown	Unknown	Survey Response	U	U	G	GRR								
211 S. Main St.	N/A	N	N	Unknown	Unknown	Visual Inspection	U	U	G	GRR								
213 S. Main St.	N/A	N	N	Unknown	Unknown	Visual Inspection	U	U	L	L								
310 S. Main St.	N/A	N	N	Unknown	Unknown	Visual Inspection	U	U	G	GRR								
208 E. Market St.	N/A	N	N	Unknown	Unknown	Visual Inspection	U	U	G	GRR								

302 E. Market St.	N/A	N	N	Unknown	Unknown	Visual Inspection	U	U	G	GRR								
304 E. Market St.	N/A	N	N	Unknown	Unknown	Visual Inspection	U	U	G	GRR								
108 W. Market St.	N/A	N	N	2020	Unknown	Visual Inspection	Plastic	P	L	L								
204 W. Market St.	N/A	N	N	2020	Unknown	Visual Inspection	Plastic	P	C	NL								
209 W. Market St.	N/A	N	N	2020	Unknown	Visual Inspection	Plastic	P	G	GRR								
210 W. Market St.	N/A	N	N	2020	Unknown	Survey Response	Plastic	P	G	GRR								
203 E. Second St.	N/A	N	N	Unknown	Unknown	Survey Response	U	U	C	U								
302 E. Second St.	N/A	N	N	2022	Unknown	Visual Inspection	Plastic	P	G	GRR								
316 E. Second St.	N/A	N	N	Unknown	Unknown	Survey Response	U	U	G	GRR								
317 E. Second St.	N/A	N	N	Unknown	Unknown	Visual Inspection	U	U	P	U								
401 E. Second St.	LA3R023	N	N	Unknown	Unknown	Visual Inspection	U	U	G	GRR								
402 E. Second St.	N/A	N	N	Unknown	Unknown	Visual Inspection	U	U	G	GRR								
408 E. Second St.	N/A	N	N	Unknown	Unknown	Visual Inspection	U	U	P	U								
502 E. Second St.	N/A	N	Y	Unknown	Unknown	Visual Inspection	U	U	P	U								
107 W. Second St.	N/A	N	N	2020	Unknown	Visual Inspection	Plastic	P	C	NL								
201 W. Second St.	N/A	N	N	2020	Unknown	Visual Inspection	Plastic	P	G	GRR								
401 W. Second St.	N/A	N	N	2020	Unknown	Visual Inspection	Plastic	P	G	GRR								
204 E. Third St.	N/A	N	N	Unknown	Unknown	Visual Inspection	U	U	G	GRR								
305 W. Third St.	LP3S012	N	N	2020	Unknown	Visual Inspection	Plastic	P	G	GRR								
306 W. Third St.	N/A	N	Y	2020	Unknown	Visual Inspection	Plastic	P	C	NL								
102 N. Washington	N/A	N	N	2020	Unknown	Visual Inspection	Plastic	P	C	NL								
108 N. Washington	N/A	N	N	2020	Unknown	Visual Inspection	Plastic	P	G	GRR								
205 N. Washington	N/A	N	Y	2020	Unknown	Visual Inspection	Plastic	P	C	NL								
100 S. Washington	N/A	N	N	2020	Unknown	Visual Inspection	Plastic	P	C	NL								
106 S. Washington	N/A	N	N	2020	Unknown	Visual Inspection	Plastic	P	C	NL								
107 S. Washington	N/A	N	N	2020	Unknown	Visual Inspection	Plastic	P	P	NL								
207 S. Washington	N/A	N	N	2020	Unknown	Survey Response	Plastic	P	G	GRR								
212 S. Washington	N/A	N	N	2020	Unknown	Visual Inspection	Plastic	P	C	NL								
315 E. Second St.	N/A	N	N	Unknown	Unknown	Visual Inspection	U	U	G	GRR								
212 S. Benton St.	N/A	N	N	2020	Unknown	Visual Inspection	Plastic	P	G	GRR								
313 E. Booth St.	N/A	N	N	Unknown	Unknown	Survey Response	U	U	C	U								
407 E. Booth St.	N/A	N	N	Unknown	Unknown	Visual Inspection	U	U	C	U								
105 S. Canal St.	N/A	N	N	Unknown	Unknown	Visual Inspection	U	U	P	U								
206 N. Fremont St.	N/A	N	N	Unknown	Unknown	Visual Inspection	U	U	G	GRR								
208 S. Fremont St.	N/A	N	N	Unknown	Unknown	Visual Inspection	U	U	C	U								
208 W. Glassburn S	N/A	N	Y	Unknown	Unknown	Visual Inspection	U	U	G	GRR								
211 S. Joy St.	N/A	N	N	Unknown	Unknown	Visual Inspection	U	U	C	U								
201 E. Kimball St.	N/A	N	N	2020	Unknown		Plastic	P	U	U								
305 E. Second St.	N/A	N	N	Unknown	Unknown	Visual Inspection	U	U	G	GRR								
404 E. Second St.	LP3S003	N	N	Unknown	Unknown	Visual Inspection	U	U	C	U								
308 E. Third St.	N/A	N	N	Unknown	Unknown	Visual Inspection	U	U	C	U								
206 S. Washington	N/A	N	N	2020	Unknown	Visual Inspection	Plastic	P	P	NL								
201 W. Glassburn S	N/A	N	N	Unknown	Unknown	Visual Inspection	U	U	P	U								
104 S. Joy St.	LP3S013	N	Y	Unknown	Unknown	Visual Inspection	U	U	C	U								
206 E. Booth St.	N/A	N	N	Unknown	Unknown	Visual Inspection	U	U	G	GRR								
109 S. Canal St.	N/A	N	N	Unknown	Unknown	Visual Inspection	U	U	G	GRR								
104 N. Lincoln St.	N/A	N	N	2020	Unknown	Visual Inspection	Plastic	P	G	GRR								
207 S. Lincoln St.	N/A	N	N	Unknown	Unknown	Visual Inspection	U	U	P	U								
208 B S. Main Pl.	N/A	N	N	Unknown	Unknown	Visual Inspection	U	U	G	GRR								
315 S. Main St.	N/A	N	N	Unknown	Unknown	Survey Response	U	U	G	GRR								
207 E. Market St.	N/A	N	N	Unknown	Unknown	Visual Inspection	U	U	G	GRR								
305 E. Market St.	N/A	N	N	Unknown	Unknown	Survey Response	U	U	G	GRR								
204 S. Washington	N/A	N	N	2020	Unknown	Visual Inspection	Plastic	P	G	GRR								
208 A S. Main Pl.	N/A	N	N	Unknown	Unknown		U	U	G	GRR								
103 S. Benton St.	N/A	N	N	2020	Unknown	Visual Inspection	Plastic	P	P	NL								
209 N. Fremont St.	N/A	N	N	Unknown	Unknown		U	U	U	U								
404 E. Market St.	N/A	N	N	2020	Unknown		Plastic	U	P	U								
103 Ross St.	N/A	N	N	Unknown	Unknown	Visual Inspection	U	U	G	GRR								
109 S. Benton St.	LP3S011	N	N	2020	Unknown	Visual Inspection	Plastic	P	C	NL								
101 E. Third St.	N/A	N	N	2020	Unknown	Visual Inspection	Plastic	P	G	GRR								
307 W. Fourth St.	N/A	N	Y	2020	Unknown	Visual Inspection	Plastic	P	G	NL								
110 N. Fremont St.	N/A	N	N	Unknown	Unknown		U	U	U	U								
206 S. Grove St.	N/A	N	Y	Unknown	Unknown	Visual Inspection	U	U	G	GRR								
103 S. Joy St.	N/A	N	N	Unknown	Unknown		U	U	U	U								
300 N. Lincoln St.	N/A	N	Y	2020	Unknown	Visual Inspection	Plastic	P	G	NL								

109 S. Main St.	N/A	N	N	2017	Unknown		Plastic	P	U	U								
104 W. Market St.	N/A	N	N	2020	Unknown		Plastic	P	U	U								
109 W. Market St.	N/A	N	N	2020	Unknown		Plastic	P	U	U								
201 W. Market St.	N/A	N	Y	2020	Unknown	Visual Inspection	Plastic	P	C	NL								
312 E. Second St.	N/A	N	Y	Unknown	Unknown	Visual Inspection	U	U	G	GRR								
111 S. Canal St.	N/A	N	Y	Unknown	Unknown	Visual Inspection	U	U	C	U								
304 N. Benton St.	N/A	N	N	2020	Unknown		Plastic	P	U	U								
102 S. Benton St.	N/A	N	Y	2020	Unknown	Visual Inspection	Plastic	P	P	NL								
104 S. Benton St.	N/A	N	N	2020	Unknown		Plastic	P	U	U								
111 S. Benton St.	N/A	N	Y	2020	Unknown	Visual Inspection	Plastic	P	C	NL								
113 S. Benton St.	N/A	N	N	2020	Unknown	Visual Inspection	Plastic	P	G	GRR								
205 S. Benton St.	N/A	N	N	2020	Unknown	Visual Inspection	Plastic	P	G	GRR								
206 S. Benton St.	N/A	N	Y	2020	Unknown	Visual Inspection	Plastic	P	G	NL								
207 S. Benton St.	N/A	N	N	2020	Unknown		Plastic	P	U	U								
209 S. Benton St.	N/A	N	N	2020	Unknown	Survey Response	Plastic	P	G	GRR								
210 S. Benton St.	N/A	N	N	2020	Unknown	Survey Response	Plastic	P	C	NL								
214 S. Benton St.	N/A	N	Y	2020	Unknown	Visual Inspection	Plastic	P	G	NL								
215 S. Benton St.	N/A	N	Y	2020	Unknown	Visual Inspection	Plastic	P	G	NL								
302 E. Booth St.	N/A	N	N	Unknown	Unknown	Survey Response	U	U	G	GRR								
310 E. Booth St.	N/A	N	N	Unknown	Unknown	Survey Response	U	U	P	U								
311 E. Booth St.	N/A	N	N	Unknown	Unknown		U	U	U	U								
314 E. Booth St.	N/A	N	N	Unknown	Unknown	Survey Response	U	U	C	U								
403 E. Booth St.	N/A	N	N	Unknown	Unknown	Survey Response	U	U	G	GRR								
406 E. Booth St.	LP1A004	N	Y	Unknown	Unknown	Visual Inspection	U	U	C	U								
211 Canal St.	N/A	N	Y	Unknown	Unknown	Visual Inspection	U	U	P	U								
101 S. Canal St.	N/A	N	N	Unknown	Unknown	Survey Response	U	U	G	GRR								
101 E. Fourth St.	N/A	N	N	2020	Unknown		Plastic	P	U	U								
105 W. Fourth St.	N/A	N	Y	2020	Unknown		Plastic	P	P	NL								
201 W. Fourth St.	N/A	N	N	2020	Unknown	Survey Response	Plastic	P	G	GRR								
205 W. Fourth St.	N/A	N	Y	2020	Unknown		Plastic	P	P	NL								
301 W. Fourth St.	N/A	N	N	2020	Unknown		Plastic	P	U	U								
104 S. Fremont St.	N/A	N	Y	Unknown	Unknown	Visual Inspection	U	U	P	U								
210 S. Fremont St.	N/A	N	N	Unknown	Unknown	Survey Response	U	U	L	L								
212 S. Fremont St.	N/A	N	N	Unknown	Unknown	Survey Response	U	U	G	GRR								
213 S. Fremont St.	N/A	N	N	2020	Unknown		Plastic	P	U	U								
204 W. Glassburn S	N/A	N	Y	Unknown	Unknown	Visual Inspection	U	U	G	GRR								
402 Glassburn St.	N/A	N	Y	2020	Unknown	Visual Inspection	Plastic	P	P	NL								
106 W. Glassburn S	N/A	N	N	Unknown	Unknown	Survey Response	U	U	G	GRR								
206 W. Glassburn S	N/A	N	N	Unknown	Unknown	Survey Response	U	U	L	L								
207 W. Glassburn S	N/A	N	N	Unknown	Unknown		U	U	U	U								
308 W. Glassburn S	N/A	N	N	2020	Unknown	Survey Response	Plastic	P	G	GRR								
102 N. Grove St.	N/A	N	Y	Unknown	Unknown	Visual Inspection	U	U	C	U								
104 S. Grove St.	N/A	N	N	Unknown	Unknown		U	U	U	U								
202 S. Grove St.	N/A	N	N	Unknown	Unknown	Survey Response	U	U	C	U								
205 S. Grove St.	N/A	N	N	Unknown	Unknown		U	U	U	U								
204 N. Joy St.	N/A	N	N	2020	Unknown	Survey Response	Plastic	P	G	GRR								
205 N. Joy St.	N/A	N	N	2020	Unknown	Survey Response	Plastic	P	G	GRR								
207 N. Joy St.	N/A	N	Y	2020	Unknown	Visual Inspection	Plastic	P	G	NL								
106 B S. Joy St.	N/A	N	N	Unknown	Unknown	Survey Response	U	U	C	U								
105 S. Joy St.	N/A	N	N	2020	Unknown	Survey Response	Plastic	P	P	NL								
106 A S. Joy St.	N/A	N	N	Unknown	Unknown	Survey Response	U	U	C	U								
210 S. Joy St.	N/A	N	Y	Unknown	Unknown	Visual Inspection	U	U	C	U								
213 S. Joy St.	N/A	N	N	Unknown	Unknown		U	U	U	U								
215 S. Joy St.	N/A	N	Y	Unknown	Unknown	Visual Inspection	U	U	P	U								
101 E. Kimball St.	N/A	N	N	Unknown	Unknown	Survey Response	U	U	C	U								
103 E. Kimball St.	N/A	N	N	Unknown	Unknown	Survey Response	U	U	C	U								
106 E. Kimball St.	N/A	N	N	Unknown	Unknown	Survey Response	U	U	C	U								
202 E. Kimball St.	N/A	N	Y	2020	Unknown	Visual Inspection	Plastic	P	G	NL								
303 E. Kimball St.	N/A	N	N	2020	Unknown	Survey Response	Plastic	P	C	NL								
206 W. Kimball St.	N/A	N	N	Unknown	Unknown	Survey Response	U	U	G	GRR								
308 W. Kimball St.	N/A	N	N	Unknown	Unknown		U	U	U	U								
400 W. Kimball St.	N/A	N	Y	Unknown	Unknown	Visual Inspection	U	U	G	GRR								
106 N. Lincoln St.	N/A	N	N	2020	Unknown	Survey Response	Plastic	P	G	GRR								
201 N. Lincoln St.	N/A	N	Y	2020	Unknown	Visual Inspection	Plastic	P	G	NL								
202 N. Lincoln St.	N/A	N	Y	2020	Unknown	Visual Inspection	Plastic	P	C	NL								

206 N. Lincoln St.	N/A	N	Y	2020	Unknown	Visual Inspection	Plastic	P	G	NL								
208 N. Lincoln St.	N/A	N	N	2020	Unknown		Plastic	P	U	U								
106 S. Lincoln St.	N/A	N	N	Unknown	Unknown	Survey Response	U	U	G	GRR								
108 S. Lincoln St.	N/A	N	Y	Unknown	Unknown	Visual Inspection	U	U	P	U								
204 S. Lincoln St.	N/A	N	N	Unknown	Unknown		U	U	U	U								
206 S. Lincoln St.	N/A	N	N	Unknown	Unknown		U	U	U	U								
206 B S. Main Pl.	N/A	N	N	Unknown	Unknown	Visual Inspection	U	U	C	U								
106 N. Main St.	N/A	N	N	2020	Unknown	Survey Response	Plastic	P	G	GRR								
108 N. Main St.	N/A	N	Y	2020	Unknown	Visual Inspection	Plastic	P	G	NL								
210 N. Main St.	N/A	N	N	2020	Unknown	Survey Response	Plastic	P	C	NL								
302 N. Main St.	N/A	N	N	2020	Unknown		Plastic	P	U	U								
303 N. Main St.	N/A	N	Y	2020	Unknown	Visual Inspection	Plastic	P	G	NL								
305 N. Main St.	N/A	N	N	2020	Unknown	Survey Response	Plastic	P	G	GRR								
309 N. Main St.	N/A	N	Y	2020	Unknown	Visual Inspection	Plastic	P	C	NL								
312 N. Main St.	N/A	N	N	2020	Unknown	Survey Response	Plastic	P	G	GRR								
406 N. Main St.	N/A	N	N	2020	Unknown	Survey Response	Plastic	P	G	GRR								
108 S. Main St.	N/A	N	N	Unknown	Unknown		U	U	U	U								
126 S. Main St.	N/A	N	N	2020	2022	Survey Response	Plastic	P	P	NL								
202 S. Main St.	N/A	N	N	Unknown	Unknown		U	U	U	U								
207 S. Main St.	N/A	N	Y	Unknown	Unknown	Visual Inspection	U	U	G	GRR								
303 S. Main St.	N/A	N	N	Unknown	Unknown	Survey Response	U	U	G	GRR								
307 S. Main St.	N/A	N	Y	Unknown	Unknown	Visual Inspection	U	U	U	U								
309 S. Main St.	N/A	N	N	Unknown	Unknown	Survey Response	U	U	C	U								
312 S. Main St.	N/A	N	N	Unknown	Unknown		U	U	U	U								
314 S. Main St.	N/A	N	Y	Unknown	Unknown	Visual Inspection	U	U	G	GRR								
316 S. Main St.	N/A	N	N	Unknown	Unknown		U	U	U	U								
100 E. Market St.	LP35014	N	N	2020	Unknown	Survey Response	Plastic	P	C	NL								
201 E. Market St.	N/A	N	N	2020	Unknown		Plastic	P	U	U								
306 E. Market St.	N/A	N	N	Unknown	Unknown	Survey Response	U	U	L	L								
308 E. Market St.	N/A	N	N	Unknown	Unknown	Survey Response	U	U	G	GRR								
309 E. Market St.	N/A	N	N	Unknown	Unknown	Survey Response	U	U	C	U								
310 E. Market St.	N/A	N	N	Unknown	Unknown	Survey Response	U	U	G	GRR								
401 E. Market St.	N/A	N	N	Unknown	Unknown	Survey Response	U	U	G	GRR								
406 E. Market St.	N/A	N	N	Unknown	Unknown	Survey Response	U	U	P	U								
407 E. Market St.	N/A	N	Y	Unknown	Unknown	Visual Inspection	U	U	C	U								
408 E. Market St.	N/A	N	N	Unknown	Unknown		U	U	U	U								
409 E. Market St.	N/A	N	N	Unknown	Unknown		U	U	U	U								
106 W. Market St.	N/A	N	N	2020	Unknown		Plastic	P	U	U								
207 W. Market St.	N/A	N	N	2020	Unknown		Plastic	P	U	U								
309 W. Market St.	N/A	N	N	2020	Unknown		Plastic	P	U	U								
301 E. Second St.	N/A	N	N	Unknown	Unknown	Survey Response	U	U	C	U								
307 E. Second St.	N/A	N	Y	Unknown	Unknown	Visual Inspection	U	U	G	GRR								
308 E. Second St.	N/A	N	N	Unknown	Unknown		U	U	U	U								
309 E. Second St.	N/A	N	N	Unknown	Unknown	Survey Response	U	U	C	U								
310 E. Second St.	N/A	N	N	Unknown	Unknown	Survey Response	U	U	G	GRR								
311 E. Second St.	N/A	N	N	Unknown	Unknown		U	U	U	U								
406 E. Second St.	N/A	N	N	Unknown	Unknown	Survey Response	U	U	C	U								
104 E. Third St.	N/A	N	Y	2020	Unknown	Visual Inspection	Plastic	P	P	NL								
202 E. Third St.	N/A	N	N	Unknown	Unknown	Survey Response	U	U	G	GRR								
304 E. Third St.	N/A	N	Y	Unknown	Unknown	Visual Inspection	U	U	P	U								
306 E. Third St.	N/A	N	N	Unknown	Unknown	Survey Response	U	U	C	U								
105 W. Third St.	N/A	N	N	2020	Unknown		Plastic	P	U	U								
201 W. Third St.	N/A	N	N	2020	Unknown		Plastic	P	U	U								
211 W. Third St.	N/A	N	N	2020	Unknown		Plastic	P	U	U								
103 N. Washington	N/A	N	N	2020	Unknown		Plastic	P	U	U								
107 N. Washington	N/A	N	N	2020	Unknown		Plastic	P	U	U								
208 N. Washington	N/A	N	N	2020	Unknown		Plastic	P	U	U								
103 S. Washington	N/A	N	N	2020	Unknown		Plastic	P	U	U								
110 S. Washington	N/A	N	N	2020	2024	Cosntruction Records	Plastic	P	P	NL								
203 S. Washington	N/A	N	N	2020	Unknown		Plastic	P	U	U								
208 S. Washington	N/A	N	Y	2020	Unknown	Visual Inspection	Plastic	P	C	NL								
210 S. Washington	N/A	N	Y	2020	Unknown	Visual Inspection	Plastic	P	G	NL								
305 N. Joy St.	N/A	N	Y	2020	Unknown	Visual Inspection	Plastic	P	G	NL								
301 E. Market St.	N/A	N	N	Unknown	Unknown		U	U	U	U								
304 W. Market St.	N/A	N	Y	2020	Unknown	Visual Inspection	Plastic	P	G	NL								

101, 103, 105 N Main St	N/A	N	N	Unknown	Unknown		U	U	U	U								
107 N. Main St.	N/A	N	N	Unknown	Unknown		U	U	U	U								
123 S. Main St.	N/A	N	N	2020	Unknown		Plastic	P	U	U								
304 E. Kimball St.	N/A	Y	N	2020	Unknown	Visual Inspection	Plastic	P	Unknown	G	GRR							
115 S. Main St.	N/A	N	N	2020	Unknown	Visual Inspection	Plastic	P	Unknown	G	GRR							
111 N. Main St.	N/A	N	N	Unknown	Unknown	Visual Inspection	U	U	Unknown	G	GRR							
105 S. Main St.	N/A	N	Y	2020	Unknown	Visual Inspection	Plastic	P	Unknown	C	NL							
111 S. Main St.	N/A	N	N	2020	Unknown	Visual Inspection	Plastic	P	Unknown	G	GRR							
112-120 S. Main St.	LP1A006	N	N	2020	Unknown	Visual Inspection	Plastic	P	Unknown	C	NL							
201 N. Benton St.	N/A	N	N	Unknown	Unknown	Visual Inspection	U	U	Unknown	G	GRR							
103 E. Fourth St.	N/A	N	N	2020	Unknown	Visual Inspection	Plastic	P	Unknown	G	GRR							
102 N. Main St.	N/A	N	N	2020	Unknown	Visual Inspection	Plastic	P	Unknown	C	NL							
122 S. Main St.	N/A	N	N	2020	Unknown	Visual Inspection	Plastic	P	Unknown	C	NL							
107 S. Main St.	N/A	N	N	2020	Unknown	Visual Inspection	Plastic	P	Unknown	G	GRR							
201 S. Main St.	N/A	N	N	Unknown	Unknown	Visual Inspection	U	U	Unknown	C	U							
200 S. Lincoln St.	N/A	N	N	Unknown	Unknown		U	U	Unknown	U	U							
111 S. Main St.	N/A	N	N	Unknown	Unknown		U	U	Unknown	U	U							
310 E. Third St.	N/A	N	N	Unknown	Unknown	Visual Inspection	U	U	Unknown	G	GRR							
110 S. Benton St.	N/A	N	N	2020	Unknown	Visual Inspection	Plastic	P	Unknown	G	GRR							
106 S. Main St.	N/A	N	N	2020	Unknown	Visual Inspection	Plastic	P	Unknown	C	NL							
106 S. Fremont St.	N/A	N	N	Unknown	Unknown		U	U	Unknown	U	U							
505 W. Kimball St.	N/A	N	N	Unknown	Unknown	Visual Inspection	U	U	Unknown	P	U							
401 N. Washington	N/A	N	N	2020	Unknown	Survey Response	Plastic	P	Unknown	C	NL							
207 W. Third St.	N/A	N	Y	2020	Unknown	Visual Inspection	Plastic	P	Unknown	G	NL							
403 E. Market St.	N/A	N	N	Unknown	Unknown		U	U	Unknown	U	U							
308 E. Booth St.	N/A	N	Y	Unknown	Unknown	Visual Inspection	U	U	Unknown	G	GRR							
104 Ross St.	N/A	N	N	Unknown	Unknown		U	U	Unknown	U	U							
107 W. Market St.	N/A	N	N	2020	Unknown		Plastic	P	Unknown	U	U							
203 S. Main St.	N/A	N	N	Unknown	Unknown		U	U	Unknown	U	U							
401 N. Main St.	N/A	N	N	Unknown	Unknown		U	U	Unknown	U	U							
109 N. Main St.	N/A	N	N	Unknown	Unknown		U	U	Unknown	U	U							
404 W. Kimball St.	N/A	N	N	Unknown	Unknown		U	U	Unknown	U	U							
105 W. Market St.	N/A	N	N	2020	Unknown		Plastic	P	Unknown	U	U							
109 S. Washington	N/A	N	N	2020	Unknown		Plastic	P	Unknown	U	U							
117 S. Main St.	N/A	N	N	2020	Unknown		Plastic	P	Unknown	U	U							
205+ S. Fremont St.	N/A	N	N	Unknown	Unknown		U	U	Unknown	U	U							
307 N. Main St.	N/A	N	N	2020	Unknown	Visual Inspection	Plastic	P	Unknown	G	GRR							
202 W. Second St.	N/A	N	N	2020	Unknown	Visual Inspection	Plastic	P	Unknown	G	GRR							
107 E. Market St.	N/A	N	N	2020	Unknown		Plastic	P	Unknown	U	U							
203 S. Benton St.	N/A	N	N	2020	Unknown	Visual Inspection	Plastic	P	Unknown	P	NL							
203 W. Market St.	N/A	N	N	2020	Unknown	Visual Inspection	Plastic	P	Unknown	C	NL							
304 W. Kimball St.	N/A	N	N	Unknown	2023	Visual Inspection	U	G	Unknown	P	GRR							
218 S. Benton St.	N/A	N	N	2020	Unknown		Plastic	P	Unknown	U	U							
104 N. Washington	N/A	N	N	2020	Unknown		Plastic	P	Unknown	U	U							
304 W. Third St.	N/A	N	N	2020	Unknown		Plastic	P	Unknown	U	U							
306 E. Second St.	N/A	N	N	Unknown	Unknown	Survey Response	U	U	Unknown	C	U							
320 S. Main St.	N/A	N	N	Unknown	Unknown		U	U	Unknown	U	U							
110 S. Lincoln St.	N/A	N	N	Unknown	Unknown		U	U	Unknown	U	U							
205 S. Washington	N/A	N	N	2020	Unknown		Plastic	P	Unknown	U	U							
203 N. Lincoln St.	N/A	N	N	2020	Unknown		Plastic	P	Unknown	U	U							
107 S. Joy St.	N/A	N	N	Unknown	Unknown		U	U	Unknown	U	U							
119 S. Main St.	N/A	N	N	2020	Unknown		Plastic	P	Unknown	U	U							
125 S. Main St.	N/A	N	N	2020	Unknown		Plastic	P	Unknown	U	U							
200 N. Benton St.	N/A	N	N	2020	Unknown		Plastic	P	Unknown	U	U							
123+ S. Main Street	N/A	N	N	2020	Unknown		Plastic	P	Unknown	U	U							
130 S. Main St.	N/A	N	N	Unknown	Unknown	Visual Inspection	U	U	Unknown	C	U							
301 E. Booth St.	N/A	N	N	Unknown	Unknown	Visual Inspection	U	U	Unknown	C	U							
202 S. Lincoln St.	N/A	N	N	Unknown	Unknown		U	U	Unknown	U	U							
127 S. Main St.	N/A	N	N	Unknown	Unknown	Survey Response	U	U	Unknown	G	GRR							
113 S. Main	N/A	N	N	2020	Unknown		Plastic	P	Unknown	U	U							