



Lead Service Line Inventory Template

*Please enter information in the empty box next to each section	Water System Name		Village of Tampico			System ID Number:		1950550		Current Inventory Date:		5/13/2026			
*Please enter totals in the empty box next to each category	Total Service lines:	336	Total Lead:	7	Total Non-Lead:	73	Total Galvanized Requiring replacement:	158	Total Unknown:	98	Website link to Material Inventory:				

Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property
		<b>EXAMPLES:</b> Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities  Yes (Y) or No (N)	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? <b>EXAMPLES:</b> Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	<b>EXAMPLES:</b> Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	<b>EXAMPLES:</b> Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	<b>EXAMPLES:</b> Copper - Lead Solder (CLS) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	<b>EXAMPLES:</b> Lead (L) Galvanized Requiring Replacement (GRR) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	<b>EXAMPLES:</b> Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
EXAMPLE- 123 Main Street, Citytown, 61234	N/A	N	N	2023	2023	Maintenance Records	C	P	P	NL	N	4/1/2020	Y	2/10/2023	C		
EXAMPLE- 456 Left Street, Citytown, 61234	LP3S001	Y	N	1995	1995	Construction Records	G	P	P	NL	N	N/R	N				
EXAMPLE- 789 Right Street, Citytown, 61234	N/A	N	N	1990	1990	Historical Records	UNL	UNL	UNL	NL	N	N/R	N				
EXAMPLE- 101 Middle Road, Citytown, 61234	N/A	N	N	Unknown	Unknown		U	U	U	U		N/R	N				
312 E. Booth St.	N/A	N	N	Unknown	Unknown	Visual Inspection	U	U	P	U		N/R	N			N	
402 E. Booth St.	N/A	N	N	Unknown	Unknown	Visual Inspection	U	U	C	U		N/R	N			N	
103 S. Canal St.	N/A	N	N	Unknown	Unknown	Visual Inspection	U	U	GRR	GRR		N/R	N			N	
204 N. Fremont St.	N/A	N	N	Unknown	Unknown	Visual Inspection	U	U	GRR	GRR		N/R	N			N	
201 S. Fremont St.	N/A	N	N	Unknown	Unknown	Visual Inspection	U	U	C	U		N/R	N			N	
206 S. Fremont St.	N/A	N	N	Unknown	Unknown	Visual Inspection	U	U	C	U		N/R	N			N	
209 S. Fremont St.	N/A	N	N	Unknown	Unknown	Visual Inspection	U	U	P	U		N/R	N			N	
211 S. Fremont St.	N/A	N	N	Unknown	Unknown	Visual Inspection	U	U	C	U		N/R	N			N	
104 W. Glassburn S	LC3T010	N	N	Unknown	Unknown	Visual Inspection	U	U	GRR	GRR		N/R	N			N	
106 S. Grove St.	N/A	N	N	Unknown	Unknown	Visual Inspection	U	U	GRR	GRR		N/R	N			N	
208 N. Joy St.	N/A	N	Y	2020	Unknown	Visual Inspection	Plastic	P	GRR	NL		N/R	N			N	
204 E. Kimball St.	N/A	N	N	2020	Unknown	Visual Inspection	Plastic	P	P	NL		N/R	N			N	
204 W. Kimball St.	N/A	N	N	Unknown	Unknown	Visual Inspection	U	U	GRR	GRR		N/R	N			N	
306 W. Kimball St.	N/A	N	N	Unknown	Unknown	Visual Inspection	U	U	GRR	GRR		N/R	N			N	
203 S. Lincoln St	N/A	N	N	Unknown	Unknown	Visual Inspection	U	U	GRR	GRR		N/R	N			N	
210 S. Lincoln St.	N/A	N	N	Unknown	Unknown	Visual Inspection	U	U	GRR	GRR		N/R	N			N	
201 N. Main St.	N/A	N	N	2020	Unknown	Visual Inspection	Plastic	P	GRR	GRR		N/R	N			N	
209 S. Main St.	N/A	N	N	Unknown	Unknown	Visual Inspection	U	U	GRR	GRR		N/R	N			N	
214 S. Main St.	N/A	N	N	Unknown	Unknown	Survey Response	U	U	C	U		N/R	N			N	
311 S. Main St.	N/A	N	N	Unknown	Unknown	Visual Inspection	U	U	GRR	GRR		N/R	N			N	
311 E. Market St.	N/A	N	N	Unknown	Unknown	Visual Inspection	U	U	GRR	GRR		N/R	N			N	
314 E. Market St.	N/A	N	N	Unknown	Unknown	Visual Inspection	U	U	C	U		N/R	N			N	
405 E. Market St.	LC3T018	N	N	Unknown	Unknown	Visual Inspection	U	U	GRR	GRR		N/R	N			N	
108 S. Washington	N/A	N	N	2020	Unknown	Visual Inspection	Plastic	P	GRR	GRR		N/R	N			N	
104 N. Benton St.	N/A	N	N	2020	Unknown	Visual Inspection	Plastic	P	C	NL		N/R	N			N	
105 N. Benton St.	N/A	N	N	2020	Unknown	Visual Inspection	Plastic	P	GRR	GRR		N/R	N			N	
106 N. Benton St.	N/A	N	N	2020	Unknown	Survey Response	Plastic	P	GRR	GRR		N/R	N			N	
204 N. Benton St.	N/A	N	Y	2020	Unknown	Visual Inspection	Plastic	C	GRR	GRR		N/R	N			N	

205 N. Benton St.	N/A	N	N	2020	Unknown	Survey Response	Plastic	P	GRR	GRR		N/R	N			N	
207 N. Benton St.	N/A	N	N	2020	Unknown	Visual Inspection	Plastic	P	P	NL		N/R	N			N	
107 S. Benton St.	N/A	N	N	2020	Unknown	Survey Response	Plastic	P	GRR	GRR		N/R	N			N	
201 S. Benton St.	N/A	N	N	2020	Unknown	Visual Inspection	Plastic	P	P	NL		N/R	N			N	
208 S. Benton St.	N/A	N	N	2020	Unknown	Visual Inspection	Plastic	P	GRR	GRR		N/R	N			N	
213 S. Benton St.	N/A	N	N	2020	Unknown	Visual Inspection	Plastic	P	P	NL		N/R	N			N	
216 S. Benton St.	N/A	N	N	2020	Unknown	Visual Inspection	Plastic	P	C	NL		N/R	N			N	
202 E. Booth St.	N/A	N	N	Unknown	Unknown	Visual Inspection	U	U	GRR	GRR		N/R	N			N	
304 E. Booth St.	N/A	N	N	Unknown	Unknown	Visual Inspection	U	U	C	U		N/R	N			N	
315 E. Booth St.	N/A	N	N	Unknown	Unknown	Visual Inspection	U	U	P	U		N/R	N			N	
401 E. Booth St.	N/A	N	N	Unknown	Unknown	Visual Inspection	U	U	P	U		N/R	N			N	
411 E. Booth St.	N/A	N	N	Unknown	Unknown	Visual Inspection	U	U	GRR	GRR		N/R	N			N	
104 E. Fourth St.	N/A	N	N	2020	Unknown	Visual Inspection	Plastic	P	C	NL		N/R	N			N	
106 W. Fourth St.	N/A	N	N	2020	Unknown	Visual Inspection	Plastic	P	C	NL		N/R	N			N	
202 W. Fourth St.	N/A	N	N	2020	Unknown	Visual Inspection	Plastic	P	P	NL		N/R	N			N	
303 W. Fourth St.	N/A	N	N	2020	Unknown	Survey Response	Plastic	P	C	NL		N/R	N			N	
304 W. Fourth St.	N/A	N	N	2020	Unknown	Visual Inspection	Plastic	P	C	NL		N/R	N			N	
305 W. Fourth St.	N/A	N	N	2020	Unknown	Visual Inspection	Plastic	P	GRR	GRR		N/R	N			N	
106 N. Fremont St.	N/A	N	Y	Unknown	Unknown	Visual Inspection	U	U	P	U		N/R	N			N	
108 N. Fremont St.	N/A	N	N	Unknown	Unknown	Survey Response	U	U	C	U		N/R	N			N	
103 S. Fremont St.	N/A	N	N	Unknown	Unknown	Visual Inspection	U	U	P	U		N/R	N			N	
108 S. Fremont St.	N/A	N	N	Unknown	Unknown	Visual Inspection	U	U	C	U		N/R	N			N	
110 S. Fremont St.	N/A	N	N	Unknown	Unknown	Visual Inspection	U	U	GRR	GRR		N/R	N			N	
205 S. Fremont St.	N/A	N	N	Unknown	Unknown	Visual Inspection	U	U	C	U		N/R	N			N	
202 W. Glassburn S	N/A	N	N	Unknown	Unknown	Visual Inspection	U	U	GRR	GRR		N/R	N			N	
307 W. Glassburn S	N/A	N	N	Unknown	Unknown	Visual Inspection	U	U	C	U		N/R	N			N	
108 N. Grove St.	N/A	N	N	Unknown	Unknown	Visual Inspection	U	U	C	U		N/R	N			N	
102 S. Grove St.	N/A	N	N	Unknown	Unknown	Visual Inspection	U	U	C	U		N/R	N			N	
200 S. Grove St.	N/A	N	N	Unknown	Unknown	Visual Inspection	U	U	C	U		N/R	N			N	
306 N. Joy St.	N/A	N	Y	2020	Unknown	Visual Inspection	Plastic	P	P	NL		N/R	N			N	
307 N. Joy St.	N/A	N	N	2020	Unknown	Visual Inspection	Plastic	P	C	NL		N/R	N			N	
106 S. Joy St.	N/A	N	N	Unknown	Unknown	Survey Response	U	U	GRR	GRR		N/R	N			N	
208 S. Joy St.	N/A	N	N	Unknown	Unknown	Visual Inspection	U	U	P	U		N/R	N			N	
209 S. Joy St.	N/A	N	N	Unknown	Unknown	Visual Inspection	U	U	C	U		N/R	N			N	
100 W. Kimball	N/A	N	N	Unknown	Unknown	Survey Response	U	U	GRR	GRR		N/R	N			N	
104 E. Kimball St.	N/A	N	N	Unknown	Unknown	Visual Inspection	U	U	P	U		N/R	N			N	
307 E. Kimball St.	N/A	N	N	2020	Unknown	Visual Inspection	Plastic	P	P	NL		N/R	N			N	
308 E. Kimball St.	N/A	N	N	2020	Unknown	Visual Inspection	Plastic	P	C	NL		N/R	N			N	
105 W. Kimball St.	N/A	N	N	Unknown	Unknown	Visual Inspection	U	U	GRR	GRR		N/R	N			N	
202 W. Kimball St.	N/A	N	N	Unknown	Unknown	Visual Inspection	U	U	GRR	GRR		N/R	N			N	
302 W. Kimball St.	N/A	N	N	Unknown	Unknown	Visual Inspection	U	U	GRR	GRR		N/R	N			N	
307 W. Kimball St.	N/A	N	N	2020	Unknown	Visual Inspection	Plastic	P	C	NL		N/R	N			N	
406 W. Kimball St.	N/A	N	N	Unknown	Unknown	Visual Inspection	U	U	C	U		N/R	N			N	
408 W. Kimball St.	N/A	N	N	Unknown	Unknown	Survey Response	U	U	C	U		N/R	N			N	
501 W. Kimball St.	N/A	N	N	Unknown	Unknown	Visual Inspection	U	U	GRR	GRR		N/R	N			N	
108 N. Lincoln St.	LC3T011	N	N	2020	Unknown	Visual Inspection	Plastic	P	GRR	GRR		N/R	N			N	
205 N. Lincoln St.	LC1T003	N	N	2020	Unknown	Visual Inspection	Plastic	P	L	L		N/R	N			N	
305 N. Lincoln St.	N/A	N	N	2020	Unknown	Visual Inspection	Plastic	P	GRR	GRR		N/R	N			N	
308 N. Lincoln St.	N/A	N	N	2020	Unknown	Visual Inspection	Plastic	P	GRR	GRR		N/R	N			N	
205 S. Lincoln St.	N/A	N	N	Unknown	Unknown	Visual Inspection	U	U	L	L		N/R	N			N	
208 S. Lincoln St.	N/A	N	N	Unknown	Unknown	Visual Inspection	U	U	C	U		N/R	N			N	
212 S. Lincoln St.	N/A	N	N	Unknown	Unknown	Visual Inspection	U	U	GRR	GRR		N/R	N			N	
206 A S. Main Pl.	N/A	N	N	Unknown	Unknown	Visual Inspection	U	U	C	U		N/R	N			N	
205 N. Main St.	N/A	N	N	2020	Unknown	Survey Response	Plastic	P	GRR	GRR		N/R	N			N	
206 N. Main St.	N/A	N	N	2020	Unknown	Visual Inspection	Plastic	P	C	NL		N/R	N			N	
209 N. Main St.	N/A	N	N	2020	Unknown	Visual Inspection	Plastic	P	GRR	GRR		N/R	N	10/21/2025	P	N	
212 N. Main St.	N/A	N	N	2020	Unknown	Visual Inspection	Plastic	P	GRR	GRR		N/R	N			N	
306 N. Main St.	N/A	N	N	2020	Unknown	Visual Inspection	Plastic	P	GRR	GRR		N/R	N			N	
205 S. Main St.	LC3T012	N	N	Unknown	Unknown	Visual Inspection	U	U	GRR	GRR		N/R	N			N	
206 S. Main St.	N/A	N	N	Unknown	Unknown	Survey Response	U	U	GRR	GRR		N/R	N			N	
211 S. Main St.	N/A	N	N	Unknown	Unknown	Visual Inspection	U	U	GRR	GRR		N/R	N			N	
213 S. Main St.	N/A	N	N	Unknown	Unknown	Visual Inspection	U	U	L	L		N/R	N			N	
310 S. Main St.	N/A	N	N	Unknown	Unknown	Visual Inspection	U	U	GRR	GRR		N/R	N			N	
208 E. Market St.	N/A	N	N	Unknown	Unknown	Visual Inspection	U	U	GRR	GRR		N/R	N			N	
302 E. Market St.	N/A	N	N	Unknown	Unknown	Visual Inspection	U	U	GRR	GRR		N/R	N			N	

304 E. Market St.	N/A	N	N	Unknown	Unknown	Visual Inspection	U	U	GRR	GRR		N/R	N			N	
108 W. Market St.	N/A	N	N	2020	Unknown	Visual Inspection	Plastic	P	L	L		N/R	N			N	
204 W. Market St.	N/A	N	N	2020	Unknown	Visual Inspection	Plastic	P	C	NL		N/R	N			N	
209 W. Market St.	N/A	N	N	2020	Unknown	Visual Inspection	Plastic	P	GRR	GRR		N/R	N			N	
210 W. Market St.	N/A	N	N	2020	Unknown	Survey Response	Plastic	P	GRR	GRR		N/R	N			N	
203 E. Second St.	N/A	N	N	Unknown	Unknown	Survey Response	U	U	C	U		N/R	N			N	
302 E. Second St.	N/A	N	N	2022	Unknown	Visual Inspection	Plastic	P	GRR	GRR		N/R	N			N	
316 E. Second St.	N/A	N	N	Unknown	Unknown	Survey Response	U	U	GRR	GRR		N/R	N			N	
317 E. Second St.	N/A	N	N	Unknown	Unknown	Visual Inspection	U	U	P	U		N/R	N			N	
401 E. Second St.	LC3T019	N	N	Unknown	Unknown	Visual Inspection	U	U	GRR	GRR		N/R	N			N	
402 E. Second St.	N/A	N	N	Unknown	Unknown	Visual Inspection	U	U	GRR	GRR		N/R	N			N	
408 E. Second St.	N/A	N	N	Unknown	Unknown	Visual Inspection	U	U	P	U		N/R	N			N	
502 E. Second St.	N/A	N	Y	Unknown	Unknown	Visual Inspection	U	U	P	U		N/R	N			N	
107 W. Second St.	N/A	N	N	2020	Unknown	Visual Inspection	Plastic	P	C	NL		N/R	N			N	
201 W. Second St.	N/A	N	N	2020	Unknown	Visual Inspection	Plastic	P	GRR	GRR		N/R	N			N	
401 W. Second St.	N/A	N	N	2020	Unknown	Visual Inspection	Plastic	P	GRR	GRR		N/R	N			N	
204 E. Third St.	N/A	N	N	Unknown	Unknown	Visual Inspection	U	U	GRR	GRR		N/R	N			N	
305 W. Third St.	LC3T020	N	N	2020	Unknown	Visual Inspection	Plastic	P	GRR	GRR		N/R	N			N	
306 W. Third St.	N/A	N	Y	2020	Unknown	Visual Inspection	Plastic	P	C	NL		N/R	N			N	
102 N. Washington	N/A	N	N	2020	Unknown	Visual Inspection	Plastic	P	C	NL		N/R	N			N	
108 N. Washington	LC3T021	N	N	2020	Unknown	Visual Inspection	Plastic	P	GRR	GRR		N/R	N			N	
205 N. Washington	N/A	N	Y	2020	Unknown	Visual Inspection	Plastic	P	C	NL		N/R	N			N	
100 S. Washington	N/A	N	N	2020	Unknown	Visual Inspection	Plastic	P	C	NL		N/R	N			N	
106 S. Washington	N/A	N	N	2020	Unknown	Visual Inspection	Plastic	P	C	NL		N/R	N			N	
107 S. Washington	N/A	N	N	2020	Unknown	Visual Inspection	Plastic	P	P	NL		N/R	N			N	
207 S. Washington	N/A	N	N	2020	Unknown	Survey Response	Plastic	P	GRR	GRR		N/R	N			N	
212 S. Washington	N/A	N	N	2020	Unknown	Visual Inspection	Plastic	P	C	NL		N/R	N			N	
315 E. Second St.	N/A	N	N	Unknown	Unknown	Visual Inspection	U	U	GRR	GRR		N/R	N			N	
212 S. Benton St.	LC3T015	N	N	2020	Unknown	Visual Inspection	Plastic	P	GRR	GRR		N/R	N			N	
313 E. Booth St.	N/A	N	N	Unknown	Unknown	Survey Response	U	U	C	U		N/R	N			N	
407 E. Booth St.	N/A	N	N	Unknown	Unknown	Visual Inspection	U	U	C	U		N/R	N			N	
105 S. Canal St.	N/A	N	N	Unknown	Unknown	Visual Inspection	U	U	P	U		N/R	N			N	
206 N. Fremont St.	N/A	N	N	Unknown	Unknown	Visual Inspection	U	U	GRR	GRR		N/R	N			N	
208 S. Fremont St.	N/A	N	N	Unknown	Unknown	Visual Inspection	U	U	C	U		N/R	N			N	
208 W. Glassburn S	N/A	N	Y	Unknown	Unknown	Visual Inspection	U	U	GRR	GRR		N/R	N			N	
211 S. Joy St.	N/A	N	N	Unknown	Unknown	Visual Inspection	U	U	C	U		N/R	N			N	
201 E. Kimball St.	N/A	N	Y	2020	Unknown	Visual Inspection	Plastic	P	P	NL		N/R	N			N	
305 E. Second St.	N/A	N	N	Unknown	Unknown	Visual Inspection	U	U	GRR	GRR		N/R	N			N	
404 E. Second St.	N/A	N	N	Unknown	Unknown	Visual Inspection	U	U	C	U		N/R	N			N	
308 E. Third St.	N/A	N	N	Unknown	Unknown	Visual Inspection	U	U	C	U		N/R	N			N	
206 S. Washington	N/A	N	N	2020	Unknown	Visual Inspection	Plastic	P	P	NL		N/R	N			N	
201 W. Glassburn S	N/A	N	N	Unknown	Unknown	Visual Inspection	U	U	P	U		N/R	N			N	
104 S. Joy St.	N/A	N	Y	Unknown	Unknown	Visual Inspection	U	U	C	U		N/R	N			N	
206 E. Booth St.	LC3T016	N	N	Unknown	Unknown	Visual Inspection	U	U	GRR	GRR		N/R	N			N	
109 S. Canal St.	N/A	N	N	Unknown	Unknown	Visual Inspection	U	U	GRR	GRR		N/R	N			N	
104 N. Lincoln St.	N/A	N	N	2020	Unknown	Visual Inspection	Plastic	P	GRR	GRR		N/R	N			N	
207 S. Lincoln St.	N/A	N	N	Unknown	Unknown	Visual Inspection	U	U	P	U		N/R	N			N	
208 B S. Main Pl.	N/A	N	N	Unknown	Unknown	Visual Inspection	U	U	GRR	GRR		N/R	N			N	
315 S. Main St.	N/A	N	N	Unknown	Unknown	Survey Response	U	U	GRR	GRR		N/R	N			N	
207 E. Market St.	N/A	N	N	Unknown	Unknown	Visual Inspection	U	U	GRR	GRR		N/R	N			N	
305 E. Market St.	N/A	N	N	Unknown	Unknown	Survey Response	U	U	GRR	GRR		N/R	Yes	1/8/2026	P	N	
204 S. Washington	N/A	N	N	2020	Unknown	Visual Inspection	Plastic	P	GRR	GRR		N/R	N			N	
208 A S. Main Pl.	LC3T013	N	N	Unknown	Unknown		U	U	GRR	GRR		N/R	N			N	
103 S. Benton St.	N/A	N	N	2020	Unknown	Visual Inspection	Plastic	P	P	NL		N/R	N			N	
404 E. Market St.	N/A	N	N	2020	Unknown		Plastic	U	P	U		N/R	N			N	
103 Ross St.	N/A	N	N	Unknown	Unknown	Visual Inspection	U	U	GRR	GRR		N/R	N			N	
109 S. Benton St.	N/A	N	N	2020	Unknown	Visual Inspection	Plastic	P	C	NL		N/R	N			N	
101 E. Third St.	N/A	N	N	2020	Unknown	Visual Inspection	Plastic	P	GRR	GRR		N/R	N			N	
307 W. Fourth St.	LC3T009	N	Y	2020	Unknown	Visual Inspection	Plastic	P	GRR	GRR		N/R	N			N	
110 N. Fremont St.	N/A	N	Y	Unknown	Unknown	Visual Inspection	U	U	GRR	GRR		N/R	N			N	
206 S. Grove St.	N/A	N	Y	Unknown	Unknown	Visual Inspection	U	U	GRR	GRR		N/R	N			N	
103 S. Joy St.	N/A	N	N	Unknown	Unknown	Visual Inspection	C	C	GRR	GRR		N/R	N			N	
300 N. Lincoln St.	N/A	N	Y	2020	Unknown	Visual Inspection	Plastic	P	GRR	GRR		N/R	N			N	
109 S. Main St.	N/A	N	N	2017	Unknown		Plastic	P	C	NL		N/R	N			N	
104 W. Market St.	N/A	N	Y	2020	Unknown	Visual Inspection	Plastic	P	GRR	GRR		N/R	N			N	

109 W. Market St.	N/A	N	N	2020	Unknown		Plastic	P	C	NL		N/R	N			N	
201 W. Market St.	N/A	N	Y	2020	Unknown	Visual Inspection	Plastic	P	C	NL		N/R	N			N	
312 E. Second St.	N/A	N	Y	Unknown	Unknown	Visual Inspection	U	U	GRR	GRR		N/R	N			N	
111 S. Canal St.	N/A	N	Y	Unknown	Unknown	Visual Inspection	U	U	C	U		N/R	N			N	
304 N. Benton St.	N/A	N	Y	2020	Unknown	Visual Inspection	Plastic	P	C	NL		N/R	N			N	
102 S. Benton St.,	N/A	N	Y	2020	Unknown	Visual Inspection	Plastic	P	P	NL		N/R	N			N	
104 S. Benton St.	N/A	N	N	2020	Unknown		Plastic	P	GRR	GRR		N/R	N			N	
111 S. Benton St.	N/A	N	Y	2020	Unknown	Visual Inspection	Plastic	P	C	NL		N/R	N			N	
113 S. Benton St.	N/A	N	N	2020	Unknown	Visual Inspection	Plastic	P	GRR	GRR		N/R	N			N	
205 S. Benton St.	N/A	N	N	2020	Unknown	Visual Inspection	Plastic	P	GRR	GRR		N/R	N			N	
206 S. Benton St.	N/A	N	Y	2020	Unknown	Visual Inspection	Plastic	P	GRR	GRR		N/R	N			N	
207 S. Benton St.	N/A	N	Y	2020	Unknown	Visual Inspection	Plastic	P	GRR	GRR		N/R	N			N	
209 S. Benton St.	N/A	N	N	2020	Unknown	Survey Response	Plastic	P	GRR	GRR		N/R	N			N	
210 S. Benton St.	N/A	N	N	2020	Unknown	Survey Response	Plastic	P	C	NL		N/R	N			N	
214 S. Benton St.	N/A	N	Y	2020	Unknown	Visual Inspection	Plastic	P	GRR	GRR		N/R	N			N	
215 S. Benton St.	N/A	N	Y	2020	Unknown	Visual Inspection	Plastic	P	GRR	GRR		N/R	N			N	
302 E. Booth St.	N/A	N	N	Unknown	Unknown	Survey Response	U	U	GRR	GRR		N/R	N			N	
310 E. Booth St.	N/A	N	N	Unknown	Unknown	Survey Response	U	U	P	U		N/R	N			N	
311 E. Booth St.	N/A	N	Y	Unknown	Unknown	Visual Inspection	U	U	P	U		N/R	N			N	
314 E. Booth St.	N/A	N	N	Unknown	Unknown	Survey Response	U	U	C	U		N/R	N			N	
403 E. Booth St.	N/A	N	N	Unknown	Unknown	Survey Response	U	U	GRR	GRR		N/R	N			N	
406 E. Booth St.	N/A	N	Y	Unknown	Unknown	Visual Inspection	U	U	C	U		N/R	N			N	
211 Canal St.	N/A	N	Y	Unknown	Unknown	Visual Inspection	U	U	P	U		N/R	N			N	
101 S. Canal St.	N/A	N	N	Unknown	Unknown	Survey Response	U	U	GRR	GRR		N/R	N			N	
101 E. Fourth St.	N/A	N	N	2020	Unknown	Visual Inspection	Plastic	P	C	NL		N/R	N			N	
105 W. Fourth St.	N/A	N	Y	2020	Unknown		Plastic	P	P	NL		N/R	N			N	
201 W. Fourth St.	LC3T008	N	N	2020	Unknown	Survey Response	Plastic	P	GRR	GRR		N/R	N			N	
205 W. Fourth St.	N/A	N	Y	2020	Unknown		Plastic	P	P	NL		N/R	N			N	
301 W. Fourth St.	N/A	N	Y	2020	Unknown	Visual Inspection	Plastic	P	GRR	GRR		N/R	N			N	
104 S. Fremont St.	N/A	N	N	Unknown	Unknown	Visual Inspection	U	U	P	U		N/R	N			N	
210 S. Fremont St.	LC1T001	N	N	Unknown	Unknown	Survey Response	U	U	L	L		N/R	N			N	
212 S. Fremont St.	LC3T017	N	N	Unknown	Unknown	Survey Response	U	U	GRR	GRR		N/R	N			N	
213 S. Fremont St.	N/A	N	Y	2020	Unknown	Visual Inspection	Plastic	P	C	NL		N/R	N			N	
204 W. Glassburn S	N/A	N	Y	Unknown	Unknown	Visual Inspection	U	U	GRR	GRR		N/R	N			N	
402 Glassburn St.	N/A	N	Y	2020	Unknown	Visual Inspection	Plastic	P	P	NL		N/R	N			N	
106 W. Glassburn S	N/A	N	N	Unknown	Unknown	Survey Response	U	U	GRR	GRR		N/R	N			N	
206 W. Glassburn S	LC1T002	N	N	Unknown	Unknown	Survey Response	U	U	L	L		N/R	N			N	
207 W. Glassburn S	N/A	N	Y	Unknown	Unknown	Visual Inspection	U	U	GRR	GRR		N/R	N			N	
308 W. Glassburn S	N/A	N	N	2020	Unknown	Survey Response	Plastic	P	GRR	GRR		N/R	N			N	
102 N. Grove St.	N/A	N	Y	Unknown	Unknown	Visual Inspection	U	U	C	U		N/R	N			N	
104 S. Grove St.	N/A	N	N	Unknown	Unknown		U	U	C	U		N/R	N			N	
202 S. Grove St.	N/A	N	N	Unknown	Unknown	Survey Response	U	U	C	U		N/R	N			N	
205 S. Grove St.	N/A	N	Y	Unknown	Unknown	Visual Inspection	U	U	GRR	GRR		N/R	N			N	
204 N. Joy St.	N/A	N	N	2020	Unknown	Survey Response	Plastic	P	GRR	GRR		N/R	N			N	
205 N. Joy St.	N/A	N	N	2020	Unknown	Survey Response	Plastic	P	GRR	GRR		N/R	N			N	
207 N. Joy St.	N/A	N	Y	2020	Unknown	Visual Inspection	Plastic	P	GRR	GRR		N/R	N			N	
106 B S. Joy St.	N/A	N	N	Unknown	Unknown	Survey Response	U	U	C	U		N/R	N			N	
105 S. Joy St.	N/A	N	N	2020	Unknown	Survey Response	Plastic	P	P	NL		N/R	N			N	
106 A S. Joy St.	N/A	N	N	Unknown	Unknown	Survey Response	U	U	C	U		N/R	N			N	
210 S. Joy St.	N/A	N	Y	Unknown	Unknown	Visual Inspection	U	U	C	U		N/R	N			N	
213 S. Joy St.	N/A	N	Y	Unknown	Unknown	Visual Inspection	U	U	C	U		N/R	N			N	
215 S. Joy St.	N/A	N	Y	Unknown	Unknown	Visual Inspection	U	U	P	U		N/R	N			N	
101 E. Kimball St.	N/A	N	N	Unknown	Unknown	Survey Response	U	U	C	U		N/R	N			N	
103 E. Kimball St.	N/A	N	N	Unknown	Unknown	Survey Response	U	U	C	U		N/R	N			N	
106 E. Kimball St.	N/A	N	N	Unknown	Unknown	Survey Response	U	U	C	U		N/R	N			N	
202 E. Kimball St.	N/A	N	Y	2020	Unknown	Visual Inspection	Plastic	P	GRR	GRR		N/R	N			N	
303 E. Kimball St.	N/A	N	N	2020	Unknown	Survey Response	Plastic	P	C	NL		N/R	N			N	
206 W. Kimball St.	N/A	N	N	Unknown	Unknown	Survey Response	U	U	GRR	GRR		N/R	N			N	
308 W. Kimball St.	N/A	N	Y	Unknown	Unknown	Visual Inspection	U	U	GRR	GRR		N/R	N			N	
400 W. Kimball St.	N/A	N	Y	Unknown	Unknown	Visual Inspection	U	U	GRR	GRR		N/R	N			N	
106 N. Lincoln St.	N/A	N	N	2020	Unknown	Survey Response	Plastic	P	GRR	GRR		N/R	N			N	
201 N. Lincoln St.	N/A	N	Y	2020	Unknown	Visual Inspection	Plastic	P	GRR	GRR		N/R	N			N	
202 N. Lincoln St.	N/A	N	Y	2020	Unknown	Visual Inspection	Plastic	P	C	NL		N/R	N			N	
206 N. Lincoln St.	N/A	N	Y	2020	Unknown	Visual Inspection	Plastic	P	GRR	GRR		N/R	N			N	
208 N. Lincoln St.	N/A	N	Y	2020	Unknown	Visual Inspection	Plastic	P	GRR	GRR		N/R	N			N	

106 S. Lincoln St.	N/A	N	N	Unknown	Unknown	Survey Response	U	U	GRR	GRR		N/R	N			N	
108 S. Lincoln St.	N/A	N	Y	Unknown	Unknown	Visual Inspection	U	U	P	U		N/R	N			N	
204 S. Lincoln St.	N/A	N	Y	Unknown	Unknown	Visual Inspection	U	U	GRR	GRR		N/R	N			N	
206 S. Lincoln St.	N/A	N	Y	Unknown	Unknown	Visual Inspection	U	U	C	U		N/R	N			N	
206 B S. Main Pl.	N/A	N	N	Unknown	Unknown	Visual Inspection	U	U	C	U		N/R	N			N	
106 N. Main St.	N/A	N	N	2020	Unknown	Survey Response	Plastic	P	GRR	GRR		N/R	N			N	
108 N. Main St.	N/A	N	Y	2020	Unknown	Visual Inspection	Plastic	P	GRR	GRR		N/R	N			N	
210 N. Main St.	N/A	N	N	2020	Unknown	Survey Response	Plastic	P	C	NL		N/R	N			N	
302 N. Main St.	LC3T014	N	Y	2020	Unknown	Visual Inspection	Plastic	P	GRR	GRR		N/R	N			N	
303 N. Main St.	N/A	N	Y	2020	Unknown	Visual Inspection	Plastic	P	GRR	GRR		N/R	N			N	
305 N. Main St.	N/A	N	N	2020	Unknown	Survey Response	Plastic	P	GRR	GRR		N/R	N			N	
309 N. Main St.	N/A	N	Y	2020	Unknown	Visual Inspection	Plastic	P	C	NL		N/R	N			N	
312 N. Main St.	N/A	N	N	2020	Unknown	Survey Response	Plastic	P	GRR	GRR		N/R	N			N	
406 N. Main St.	N/A	N	N	2020	Unknown	Survey Response	Plastic	P	GRR	GRR		N/R	N			N	
110 S. Main St.	N/A	N	N	Unknown	Unknown		U	U	U	U		N/R	N			N	
126 S. Main St.	N/A	N	N	2020	2022	Survey Response	Plastic	P	P	NL		N/R	N			N	
202 S. Main St.	N/A	N	Y	Unknown	Unknown	Visual Inspection	U	U	C	U		N/R	N			N	
207 S. Main St.	N/A	N	Y	Unknown	Unknown	Visual Inspection	U	U	GRR	GRR		N/R	N			N	
303 S. Main St.	N/A	N	N	Unknown	Unknown	Survey Response	U	U	GRR	GRR		N/R	N			N	
309 S. Main St.	N/A	N	N	Unknown	Unknown	Survey Response	U	U	C	U		N/R	N			N	
312 S. Main St.	N/A	N	N	Unknown	Unknown		U	U	GRR	GRR		N/R	N			N	
314 S. Main St.	N/A	N	Y	Unknown	Unknown	Visual Inspection	U	U	GRR	GRR		N/R	N			N	
316 S. Main St.	N/A	N	Y	Unknown	Unknown	Survey Response	U	U	C	U		N/R	N			N	
100 E. Market St.	N/A	N	N	2020	Unknown	Survey Response	Plastic	P	C	NL		N/R	N			N	
201 E. Market St.	N/A	N	Y	2020	Unknown	Visual Inspection	Plastic	P	P	NL		N/R	N			N	
306 E. Market St.	LC1T005	N	N	Unknown	Unknown	Survey Response	U	U	L	L		N/R	N			N	
308 E. Market St.	N/A	N	N	Unknown	Unknown	Survey Response	U	U	GRR	GRR		N/R	N			N	
309 E. Market St.	N/A	N	N	Unknown	Unknown	Survey Response	U	U	C	U		N/R	N			N	
310 E. Market St.	N/A	N	N	Unknown	Unknown	Survey Response	U	U	GRR	GRR		N/R	N			N	
401 E. Market St.	N/A	N	N	Unknown	Unknown	Survey Response	U	U	GRR	GRR		N/R	N			N	
406 E. Market St.	N/A	N	N	Unknown	Unknown	Survey Response	U	U	P	U		N/R	N			N	
407 E. Market St.	N/A	N	Y	Unknown	Unknown	Visual Inspection	U	U	C	U		N/R	N			N	
408 E. Market St.	N/A	N	Y	Unknown	Unknown	Visual Inspection	U	U	P	U		N/R	N			N	
409 E. Market St.	N/A	N	Y	Unknown	Unknown	Visual Inspection	U	U	GRR	GRR		N/R	N			N	
106 W. Market St.	N/A	N	Y	2020	Unknown	Visual Inspection	Plastic	P	GRR	GRR		N/R	N			N	
207 W. Market St.	N/A	N	Y	2020	Unknown	Visual Inspection	Plastic	P	C	NL		N/R	N			N	
309 W. Market St.	N/A	N	Y	2020	Unknown	Visual Inspection	Plastic	P	GRR	GRR		N/R	N			N	
301 E. Second St.	N/A	N	N	Unknown	Unknown	Survey Response	U	U	C	U		N/R	N			N	
307 E. Second St.	N/A	N	Y	Unknown	Unknown	Visual Inspection	U	U	GRR	GRR		N/R	N			N	
308 E. Second St.	N/A	N	Y	Unknown	Unknown	Visual Inspection	U	U	C	U		N/R	N			N	
309 E. Second St.	N/A	N	N	Unknown	Unknown	Survey Response	U	U	C	U		N/R	N			N	
310 E. Second St.	N/A	N	N	Unknown	Unknown	Survey Response	U	U	GRR	GRR		N/R	N			N	
311 E. Second St.	N/A	N	Y	Unknown	Unknown	Visual Inspection	U	U	GRR	GRR		N/R	N			N	
406 E. Second St.	N/A	N	N	Unknown	Unknown	Survey Response	U	U	C	U		N/R	N			N	
104 E. Third St.	N/A	N	Y	2020	Unknown	Visual Inspection	Plastic	P	P	NL		N/R	N			N	
202 E. Third St.	N/A	N	N	Unknown	Unknown	Survey Response	U	U	GRR	GRR		N/R	N			N	
304 E. Third St.	N/A	N	Y	Unknown	Unknown	Visual Inspection	U	U	P	U		N/R	N			N	
306 E. Third St.	N/A	N	N	Unknown	Unknown	Survey Response	U	U	C	U		N/R	N			N	
105 W. Third St.	N/A	N	Y	2020	Unknown	Visual Inspection	Plastic	P	GRR	GRR		N/R	N			N	
201 W. Third St.	N/A	N	Y	2020	Unknown	Visual Inspection	Plastic	P	C	NL		N/R	N			N	
211 W. Third St.	N/A	N	N	2020	Unknown		Plastic	P	U	U		N/R	N			N	
103 N. Washington	N/A	N	Y	2020	Unknown	Visual Inspection	Plastic	P	GRR	GRR		N/R	N			N	
107 N. Washington	N/A	N	Y	2020	Unknown	Visual Inspection	Plastic	P	C	NL		N/R	N			N	
208 N. Washington	N/A	N	Y	2020	Unknown	Visual Inspection	Plastic	P	GRR	GRR		N/R	N			N	
103 S. Washington	N/A	N	Y	2020	Unknown	Visual Inspection	Plastic	P	C	NL		N/R	N			N	
110 S. Washington	N/A	N	N	2020	2024	Cosntruction Records	Plastic	P	P	NL		N/R	N			N	
203 S. Washington	N/A	N	N	2020	Unknown		Plastic	P	C	NL		N/R	N			N	
208 S. Washington	N/A	N	Y	2020	Unknown	Visual Inspection	Plastic	P	C	NL		N/R	N			N	
210 S. Washington	N/A	N	Y	2020	Unknown	Visual Inspection	Plastic	P	GRR	GRR		N/R	N			N	
305 N. Joy St.	N/A	N	Y	2020	Unknown	Visual Inspection	Plastic	P	GRR	GRR		N/R	N			N	
301 E. Market St.	N/A	N	Y	Unknown	Unknown	Visual Inspection	U	U	GRR	GRR		N/R	N			N	
304 W. Market St.	N/A	N	Y	2020	Unknown	Visual Inspection	Plastic	P	GRR	GRR		N/R	N			N	
101, 103, 105 N Main St	N/A	N	N	Unknown	Unknown		U	U	O	U		N/R	N			N	
107 N. Main St.	N/A	N	N	Unknown	Unknown		U	U	U	U		N/R	N			N	
123 S. Main St.	N/A	N	Y	2020	Unknown	Visual Inspection	Plastic	P	C	NL		N/R	N			N	

304 E. Kimball St.	N/A	Y	N	2020	Unknown	Visual Inspection	Plastic	P		GRR	GRR		N/R	N			N	
115 S. Main St.	N/A	N	N	2020	Unknown	Visual Inspection	Plastic	P		GRR	GRR		N/R	N			N	
111 N. Main St.	N/A	N	N	Unknown	Unknown	Visual Inspection	U	U		GRR	GRR		N/R	N			N	
105 S. Main St.	N/A	N	Y	2020	Unknown	Visual Inspection	Plastic	P		C	NL		N/R	N			N	
111 S. Main St.	N/A	N	Y	2020	Unknown	Visual Inspection	Plastic	P		C	NL		N/R	N			N	
112-120 S. Main St.	N/A	N	N	2020	Unknown	Visual Inspection	Plastic	P		C	NL		N/R	N			N	
201 N. Benton St.	N/A	N	N	Unknown	Unknown	Visual Inspection	U	U		GRR	GRR		N/R	N			N	
103 E. Fourth St.	N/A	N	N	2020	Unknown	Visual Inspection	Plastic	P		GRR	GRR		N/R	N			N	
102 N. Main St.	N/A	N	N	2020	Unknown	Visual Inspection	Plastic	P		C	NL		N/R	N			N	
122 S. Main St.	N/A	N	N	2020	Unknown	Visual Inspection	Plastic	P		C	NL		N/R	N			N	
107 S. Main St.	N/A	N	N	2020	Unknown	Visual Inspection	Plastic	P		GRR	GRR		N/R	N			N	
201 S. Main St.	N/A	N	N	Unknown	Unknown	Visual Inspection	U	U		C	U		N/R	N			N	
111 S. Main St.	N/A	N	Y	2020	Unknown	Construction Records	P	P		C	NL		N/R	N			N	
310 E. Third St.	N/A	N	N	Unknown	Unknown	Visual Inspection	U	U		GRR	GRR		N/R	N			N	
110 S. Benton St.	N/A	N	N	2020	Unknown	Visual Inspection	Plastic	P		GRR	GRR		N/R	N			N	
106 S. Main St.	N/A	N	N	2020	Unknown	Visual Inspection	Plastic	P		C	NL		N/R	N			N	
106 S. Fremont St.	N/A	N	Y	Unknown	Unknown	Visual Inspection	U	U		GRR	GRR		N/R	N			N	
505 W. Kimball St.	N/A	N	N	Unknown	Unknown	Visual Inspection	U	U		P	U		N/R	N			N	
401 N. Washington	N/A	N	N	2020	Unknown	Survey Response	Plastic	P		C	NL		N/R	N			N	
207 W. Third St.	N/A	N	Y	2020	Unknown	Visual Inspection	Plastic	P		GRR	GRR		N/R	N			N	
403 E. Market St.	N/A	N	Y	Unknown	Unknown		U	U		C	U		N/R	N			N	
308 E. Booth St.	N/A	N	Y	Unknown	Unknown	Visual Inspection	U	U		GRR	GRR		N/R	N			N	
104 Ross St. (Abandon Service)	N/A	N	N	Unknown	Unknown		U	U		U	U		N/R	N			N	
107 W. Market St. (Abandon Service)	N/A	N	N	2020	Unknown		Plastic	P		U	U		N/R	N			N	
203 S. Main St. (Abandon Service)	N/A	N	N	Unknown	Unknown		U	U		U	U		N/R	N			N	
404 W. Kimball St. (Abandon Service)	N/A	N	N	Unknown	Unknown		U	U		U	U		N/R	N			N	
105 W. Market St. (Abandon Service)	N/A	N	N	2020	Unknown		Plastic	P		U	U		N/R	N			N	
109 S. Washington (Abandon Service)	N/A	N	N	2020	Unknown		Plastic	P		U	U		N/R	N			N	
117 S. Main St.	N/A	N	Y	2020	Unknown	Visual Inspection	Plastic	P		C	NL		N/R	N			N	
205+ S. Fremont St.	N/A	N	N	Unknown	Unknown	Visual Inspection	C	C		C	NL		N/R	N			N	
307 N. Main St.	N/A	N	N	2020	Unknown	Visual Inspection	Plastic	P		GRR	GRR		N/R	N			N	
202 W. Second St.	N/A	N	N	2020	Unknown	Visual Inspection	Plastic	P		GRR	GRR		N/R	N			N	
203 S. Benton St.	N/A	N	N	2020	Unknown	Visual Inspection	Plastic	P		P	NL		N/R	N			N	
203 W. Market St.	N/A	N	N	2020	Unknown	Visual Inspection	Plastic	P		C	NL		N/R	N			N	
304 W. Kimball St.	N/A	N	N	Unknown	2023	Visual Inspection	U	G		P	U		N/R	N			N	
218 S. Benton St.	N/A	N	N	2020	Unknown		Plastic	P		U	U		N/R	N			N	
104 N. Washington	N/A	N	N	2020	Unknown		Plastic	P		GRR	GRR		N/R	N			N	
304 W. Third St.	N/A	N	N	2020	Unknown		Plastic	P		GRR	GRR		N/R	N			N	
306 E. Second St.	N/A	N	N	Unknown	Unknown	Survey Response	U	U		C	U		N/R	N			N	
320 S. Main St.	N/A	N	Y	Unknown	Unknown	Visual Inspection	U	U		P	U		N/R	N			N	
110 S. Lincoln St.	N/A	N	Y	Unknown	Unknown	Visual Inspection	U	U		P	U		N/R	N			N	
205 S. Washington	N/A	N	Y	2020	Unknown	Visual Inspection	Plastic	P		GRR	GRR		N/R	N			N	
123+ S. Main Street	N/A	N	Y	2020	Unknown	Visual Inspection	Plastic	P		C	NL		N/R	N			N	
130 S. Main St.	N/A	N	N	Unknown	Unknown	Visual Inspection	U	U		C	U		N/R	N			N	
301 E. Booth St.	N/A	N	N	Unknown	Unknown	Visual Inspection	U	U		C	U		N/R	N			N	
202 S. Lincoln St.	N/A	N	Y	Unknown	Unknown	Visual Inspection	U	U		P	U		N/R	N			N	
127 S. Main St.	N/A	N	N	Unknown	Unknown	Survey Response	U	U		GRR	GRR		N/R	N			N	
113 S. Main	N/A	N	Y	2020	Unknown	Visual Inspection	Plastic	P		U	U		N/R	N			N	